

MONTAGUE TOWN BRIDGES

Structure Number Last 3 Characters

BRI=Less than NBI length, usually between 10 and 20' span - meets state definition of bridge, inspected by MassDOT

CLO=Bridge is Closed, No longer Inspected as required of NBI Bridges

CUL=Culvert, less than 10' span

DUM=Dummy entry - town-line bridge is inventoried under the number for the other town in this case Erving E-10-005

NBI=National Bridge Inventory bridge - meets fed definition of bridge >20' span, requires inspection at least every 2 years (inspected by MassDOT)

PED=Pedestrian bridge, not covered by law requiring inspection of highway bridges

Open Status

A=Open

D=Open with Temporary Shoring in Place

K=Closed

P=Posted for reduced load capacity

Fracture Critical Inspection

Additional inspection focused on bridges with members that the failure of a single major tension member or member element will cause a significant portion or the entire bridge to collapse due to a lack of redundancy

Generally this applies to truss bridges

Special Member Inspection

Once the condition of the deck, superstructure, or substructure falls to a condition rating of 4 (poor) or below, that part gets inspected more frequently, every 12 months for a 4, every 6 months for a 3

MONTAGUE TOWN BRIDGES

Bridge Condition Ratings

- N NOT APPLICABLE
- 9 EXCELLENT CONDITION
- 8 VERY GOOD CONDITION - no problems noted.
- 7 GOOD CONDITION - some minor problems.
- 6 SATISFACTORY CONDITION - structural elements show some minor deterioration.
- 5 FAIR CONDITION - all primary structural elements are sound but may have minor section loss, cracking, spalling or scour.
- 4 POOR CONDITION - advanced section loss, deterioration, spalling or scour.
- 3 SERIOUS CONDITION - loss of section, deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present.
- 2 CRITICAL CONDITION - advanced deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.
- 1 "IMMINENT" FAILURE CONDITION - major deterioration or section loss present in critical structural components or obvious vertical or horizontal movement affecting structure stability. Bridge is closed to traffic but corrective action may put it back in light service.
- 0 FAILED CONDITION - out of service; beyond corrective action.

STRUCTURES INSPECTION FIELD REPORT

2-DIST 02 B.I.N. 0R2

ROUTINE & SPECIAL MEMBER INSPECTION

BR. DEPT. NO. M-28-16A

CITY/TOWN MONTAGUE	8-STRUCTURE NO. M2816A-0R2-MUN-NBI	11-Kilo. POINT 000.032	41-STATUS P:POSTED	90-ROUTINE INSP. DATE SEP 23, 2019
07-FACILITY CARRIED HWY SIXTH ST	MEMORIAL NAME/LOCAL NAME	27-YR BUILT 1988	106-YR REBUILT 0000	YR REHAB'D (NON 106) 0000
06-FEATURES INTERSECTED WATER UTILITY CANAL	26-FUNCTIONAL CLASS Urban Local	DIST. BRIDGE INSPECTION ENGINEER M. Barrett		
43-STRUCTURE TYPE 310 : Steel Truss - Thru	22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER A. R. Finck	
107-DECK TYPE 5 : Steel plate	WEATHER Clear	TEMP. (air) 26°C	TEAM MEMBERS W. MORIN	

ITEM 58		4		DEF
DECK				
1. Wearing surface	N	-		
2. Deck Condition	4	S-P		
3. Stay in Place Forms	N	-		
4. Curbs	6	-		
5. Median	N	-		
6. Sidewalks	N	-		
7. Parapets	N	-		
8. Railing	6	-		
9. Anti Missile Fence	N	-		
10. Drainage System	N	-		
11. Lighting Standards	N	-		
12. Utilities	7	-		
13. Deck Joints	N	-		
14.	N	-		
15.	N	-		
16.	N	-		
CURB REVEAL (In millimeters)		N	S	
		150	150	

ITEM 59		6		DEF
SUPERSTRUCTURE				
1. Stringers	N	-		
2. Floorbeams	7	-		
3. Floor System Bracing	7	-		
4. Girders or Beams	N	-		
5. Trusses - General	6	-		
a. Upper Chords	7	-		
b. Lower Chords	6	-		
c. Web Members	6	M-P		
d. Lateral Bracing	7	-		
e. Sway Bracings	N	-		
f. Portals	N	-		
g. End Posts	6	-		
6. Pin & Hangers	N	-		
7. Conn Plt's, Gussets & Angles	7	-		
8. Cover Plates	N	-		
9. Bearing Devices	7	-		
10. Diaphragms/Cross Frames	N	-		
11. Pins, Snap Rings	5	M-P		
12. Welds	7	-		
13. Member Alignment	7	-		
14. Paint/Coating	5	M-P		
15.	N	-		
Year Painted	N			

COLLISION DAMAGE: Please explain
None () Minor (X) Moderate () Severe ()

LOAD DEFLECTION: Please explain
None (X) Minor () Moderate () Severe ()

LOAD VIBRATION: Please explain
None (X) Minor () Moderate () Severe ()

Any Fracture Critical Member: (Y/N) **Y**

Any Cracks: (Y/N) **N**

ITEM 60		6		DEF
SUBSTRUCTURE				
1. Abutments	Dive	Cur	6	
a. Pedestals	N	N		-
b. Bridge Seats	N	6		-
c. Backwalls	N	6		-
d. Breastwalls	N	6		M-P
e. Wingwalls	N	7		-
f. Slope Paving/Rip-Rap	N	6		M-P
g. Pointing	N	N		-
h. Footings	N	N		-
i. Piles	N	H		-
j. Scour	N	7		-
k. Settlement	N	7		-
l.	N	N		-
m.	N	N		-
2. Piers or Bents				N
a. Pedestals	N	N		-
b. Caps	N	N		-
c. Columns	N	N		-
d. Stems/Webs/Pierwalls	N	N		-
e. Pointing	N	N		-
f. Footing	N	N		-
g. Piles	N	N		-
h. Scour	N	N		-
i. Settlement	N	N		-
j.	N	N		-
k.	N	N		-
3. Pile Bents				N
a. Pile Caps	N	N		-
b. Piles	N	N		-
c. Diagonal Bracing	N	N		-
d. Horizontal Bracing	N	N		-
e. Fasteners	N	N		-

UNDERMINING (Y/N) If YES please explain **Y**

COLLISION DAMAGE:
None (X) Minor () Moderate () Severe ()

SCOUR: Please explain
None (X) Minor () Moderate () Severe ()

I-60 (Dive Report): **N** I-60 (This Report): **6**

93B-U/W (DIVE) Insp **00/00/0000**

X=UNKNOWN N=NOT APPLICABLE H=HIDDEN/INACCESSIBLE R=REMOVED

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
------------------------------	----------------------	----------------------------------	---	--

ITEM 61 7

CHANNEL & CHANNEL PROTECTION

	Dive	Cur	DEF
1.Channel Scour	N	7	-
2.Embankment Erosion	N	6	M-P
3.Debris	N	6	M-P
4.Vegetation	N	N	-
5.Utilities	N	N	-
6.Rip-Rap/Slope Protection	N	N	-
7.Aggradation	N	7	-
8.Fender System	N	N	-

STREAM FLOW VELOCITY:
Tidal () High () Moderate (X) Low () None ()

ITEM 61 (Dive Report): N ITEM 61 (This Report): 7

93b-U/W INSP. DATE:

ITEM 36 TRAFFIC SAFETY

	36	COND	DEF
A. Bridge Railing	0	6	M-P
B. Transitions	0	N	-
C. Approach Guardrail	0	5	M-P
D. Approach Guardrail Ends	0	6	-

WEIGHT POSTING Not Applicable

Actual Posting:

Recommended Posting:

Waived Date: EJDMT Date:

At bridge		Other Advance	
E	W	E	W
Y	NR	Y	Y
7	7	7	7

CLEARANCE POSTING

Not Actual Field Measurement

N		S	
ft	in	ft	in
	0		0

At bridge		Advance	
N	S	N	S

ACCESSIBILITY (Y/N/P)

	Needed	Used
Lift Bucket	N	N
Ladder	N	N
Boat	N	N
Waders	N	N
Inspector 50	Y	Y
Rigging	N	N
Staging	N	N
Traffic Control	Y	Y
RR Flagger	N	N
Police	Y	Y
Other:		
	N	N

TOTAL HOURS

PLANS (Y/N): Y

(V.C.R.) (Y/N): N

TAPE#: _____

List of field tests performed:

RATING

Rating Report (Y/N): Y

Date:

Inspection data at time of existing rating
1 58: 6 1 59: 7 1 60: 7 Date :09/14/2007

(To be filled out by DBIE)

Request for Rating or Rerating (Y/N): N

If YES please give priority:
HIGH () MEDIUM () LOW ()

REASON: _____

CONDITION RATING GUIDE (For Items 58, 59, 60 and 61)

CODE	CONDITION	DEFECTS
N	NOT APPLICABLE	
G 9	EXCELLENT	Excellent condition.
G 8	VERY GOOD	No problem noted.
G 7	GOOD	Some minor problems.
F 6	SATISFACTORY	Structural elements show some minor deterioration.
F 5	FAIR	All primary structural elements are sound but may have minor section loss, cracking, spalling or scour.
P 4	POOR	Advanced section loss, deterioration, spalling or scour.
P 3	SERIOUS	Loss of section, deterioration, spalling or scour have seriously affected primary structural components. Local failures are possible. Fatigue cracks in steel or shear cracks in concrete may be present.
C 2	CRITICAL	Advanced deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.
C 1	"IMMINENT" FAILURE	Major deterioration or section loss present in critical structural components or obvious vertical or horizontal movement affecting structure stability. Bridge is closed to traffic but corrective action may put it back in light service.
0	FAILED	Out of service - beyond corrective action.

DEFICIENCY REPORTING GUIDE

DEFICIENCY: A defect in a structure that requires corrective action.

CATEGORIES OF DEFICIENCIES:

M= Minor Deficiency - Deficiencies which are minor in nature, generally do not impact the structural integrity of the bridge and could easily be repaired. Examples include but are not limited to: Spalled concrete, Minor pot holes, Minor corrosion of steel, Minor scouring, Clogged drainage, etc.

S= Severe/Major Deficiency - Deficiencies which are more extensive in nature and need more planning and effort to repair. Examples include but are not limited to: Moderate to major deterioration in concrete, Exposed and corroded rebars, Considerable settlement, Considerable scouring or undermining, Moderate to extensive corrosion to structural steel with measurable loss of section, etc.

C-S= Critical Structural Deficiency - A deficiency in a structural element of a bridge that poses an extreme unsafe condition due to the failure or imminent failure of the element which will affect the structural integrity of the bridge.

C-H= Critical Hazard Deficiency - A deficiency in a component or element of a bridge that poses an extreme hazard or unsafe condition to the public, but does not impair the structural integrity of the bridge. Examples include but are not limited to: Loose concrete hanging down over traffic or pedestrians, A hole in a sidewalk that may cause injuries to pedestrians, Missing section of bridge railing, etc.

URGENCY OF REPAIR:

I = Immediate- [Inspector(s) immediately contact District Bridge Inspection Engineer (DBIE) to report the Deficiency and to receive further instruction from him/her].

A = ASAP- [Action/Repair should be initiated by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) upon receipt of the Inspection Report].

P = Prioritize- [Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available].

2-DIST 02 B.I.N. 0R2

STRUCTURES INSPECTION FIELD REPORT
ROUTINE & SPECIAL MEMBER INSPECTION

BR. DEPT. NO. M-28-16A

CITY/TOWN MONTAGUE	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	11-Kilo. POINT 000.032	90-ROUTINE INSP. DATE Sep 23, 2019	93*-SPEC. MEMB. INSP. DATE Sep 23, 2019
07-FACILITY CARRIED HWY SIXTH ST	MEMORIAL NAME/LOCAL NAME	27-YR BUILT 1988	106-YR REBUILT 0000	*YR REHAB'D (NON 106) 0000
06-FEATURES INTERSECTED WATER UTILITY CANAL	26-FUNCTIONAL CLASS Urban Local	DIST. BRIDGE INSPECTION ENGINEER M. Barrett		
43-STRUCTURE TYPE 310 : Steel Truss - Thru	22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER S. R. Finck <i>Stephen R Finck</i>	
107-DECK TYPE 5 : Steel plate	WEATHER Clear	TEMP. (air) 26°C	TEAM MEMBERS W. MORIN <i>W. Morin</i>	

WEIGHT POSTING *Not Applicable*

H	3	3S2	Single	
Actual Posting	20	25	36	N
Recommended Posting	20	25	36	N

Waived Date: 00/00/0000 EJDMT Date: 00/00/0000

Signs In Place (Y=Yes, N=No, NR=Not Required)
 Legibility/Visibility

At bridge		Advance	
E	W	E	W
Y	NR	Y	Y
7/7		7/7	7/7

PLANS (Y/N): **Y**
 (V.C.R.) (Y/N): **N**
 TAPE#:

RATING

Rating Report (Y/N): **Y** Date: **03/01/2011**

Request for Rating or Rerating (Y/N): **N**

If YES please give priority:
 HIGH () MEDIUM () LOW ()

Inspection data at time of existing rating
 I58: 6 I59: 7 I60: 7 I62: - Date: 09/14/2007

REASON:

SPECIAL MEMBER(S):

MEMBER	CRACK (Y/N):	WELD'S CONDITION (0-9)	LOCATION OF CORROSION, SECTION LOSS (%), CRACKS, COLLISION DAMAGE, STRESS CONCENTRATION, ETC.	CONDITION		INV. RATING OF MEMBER FROM RATING ANALYSIS			Deficiencies
				PREVIOUS	PRESENT	H-20	3	3S2	
				(0-9)	(0-9)				
A	Item 58.2 - Deck Condition	N	See remarks in comments section.	5	4	20	48	75	S-P
B									
C									
D									
E									

List of field tests performed:

-

	I-58	I-59	I-60	I-62
(Overall Previous Condition)	5	6	7	-
(Overall Current Condition)	4	6	6	-

DEFICIENCY: A defect in a structure that requires corrective action.

CATEGORIES OF DEFICIENCIES:

M= Minor Deficiency - Deficiencies which are minor in nature, generally do not impact the structural integrity of the bridge and could easily be repaired. Examples include but are not limited to: Spalled concrete, Minor pot holes, Minor corrosion of steel, Minor scouring, Clogged drainage, etc.

S= Severe/Major Deficiency - Deficiencies which are more extensive in nature and need more planning and effort to repair. Examples include but are not limited to: Moderate to major deterioration in concrete, Exposed and corroded rebars, Considerable settlement, Considerable scouring or undermining, Moderate to extensive corrosion to structural steel with measurable loss of section, etc.

C-S= Critical Structural Deficiency - A deficiency in a structural element of a bridge that poses an extreme unsafe condition due to the failure or imminent failure of the element which will affect the structural integrity of the bridge.

C-H= Critical Hazard Deficiency - A deficiency in a component or element of a bridge that poses an extreme hazard or unsafe condition to the public, but does not impair the structural integrity of the bridge. Examples include but are not limited to: Loose concrete hanging down over traffic or pedestrians, A hole in a sidewalk that may cause injuries to pedestrians, Missing section of bridge railing, etc.

URGENCY OF REPAIR:

I = Immediate- [Inspector(s) immediately contact District Bridge Inspection Engineer (DBIE) to report the Deficiency and to receive further instruction from him/her].

A = ASAP- [Action/Repair should be initiated by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) upon receipt of the Inspection Report].

P = Prioritize- [Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available].

X=UNKNOWN N=NOT APPLICABLE H=HIDDEN/INACCESSIBLE R=REMOVED

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

REMARKS

BRIDGE ORIENTATION

Bridge carries Sixth Street, east to west, over the Utility Canal which flows north to south.

Trusses are labeled north and south. The 32 panels and 32 floorbeams of the ACROW panel bridge are numbered from west to east. **See Sketches 1 - 5.**

GENERAL REMARKS

Traffic Direction:

Bridge is open to one-way traffic, traveling east to west.

Weight Posting:

East Weight Posting sign acts as both the "Advance" and "At Bridge".

West Approach to the bridge has two "DO NOT ENTER" signs along with a "Advance" Weight Posting. **See Photo 1.**

ITEM 58 - DECK

Item 58.2 - Deck Condition

Deck consists of Steel Deck Panels, 27.5" wide x 5' long with five, longitudinal joists (stringers). Each longitudinal joist is 5' long, with flanges, 2" wide x 0.25" thick and webs, 4" high x 0.25" thick. **See Sketch 5.**

Each Steel Deck Unit is numbered, west to east, per panel location (area between floorbeams), and then from north to south.

Steel Deck Units:

- Have some pack rusting between the top flange of the fascia stringers and the steel panels, making the top surface bumpy.
- Some of the Steel Deck Units, have holes, near the outer edges of the panels. **See Photo 2.**
 - Panels 5 & 6, Deck Unit 4
 - Panel 31, Deck Unit 4

Deck Underside:

- Fascia Stringers have rust delamination with section loss.
- Following deck units have rust holes in the web and bottom flanges: **See Photo 3.**
 - Panel 5, Deck Unit 3
 - Panel 6, Deck Units 2, 4, & 5
 - Panels 7, 8, & 9, Deck Unit 5
 - Panel 11, Deck Unit 4
 - Panel 12, Deck Units 4 & 6
 - Panel 14, Deck Unit 2
 - Panel 22, Deck Unit 1

Anchor Clips at several locations are either broken or loose:

- Between Floorbeams 7 & 8.
- Between Floorbeams 8 & 9.
- Between Floorbeams 14 & 15.
- Between Floorbeams 17 & 18.
- Between Floorbeams 20 & 21.

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

REMARKS

Item 58.4 - Curbs

Steel Curbs are the angles along the outer edges of the steel deck. **See Sketch 3.**

Curbs have random scrape marks along the length of the bridge.

North and South Curbs, at the East End, are bent due to collision damage. **See Photo 4.**

Item 58.8 - Railing

Bridge Railing is continuous with the approach guardrail, which consists of single panel steel W-beam guardrail attached to H-posts.

Some of the bolts connected to vertical truss members and some of U-bolts are broken or missing.

South Railing & South Truss, West End, are covered by vegetation.

Item 58.12 - Utilities

2" diameter metal conduit that travels along the outside face of the South Truss.

APPROACHES

Approaches a - Appr. pavement condition

East Approach Roadway has a large HMA patch next to the concrete header.

West Approach Roadway has HMA patching along the edge of the concrete header, there is a full width transverse crack x 1/2" wide within the HMA patch.

ITEM 59 - SUPERSTRUCTURE

Item 59.2 - Floorbeams

Floorbeams have areas of minor surface rust. **See Photo 5.**

Some Floorbeams are slightly lifting up from the floorbeam bracing system. **See Photo 6.**

Item 59.3 - Floor System Bracing

Floorbeam Bracing System has areas of light rust staining. **See Photo 6.**

Item 59.5 - Trusses - General

Item 59.5.a - Upper Chords

Top surface of Upper Chords have areas of light rust staining. **See Photo 7.**

Item 59.5.b - Lower Chords

A few small dents scattered throughout the lower chord. **See Photo 8.**

North Truss, Interior Lower Chord, next to the East Backwall is bent. Appears to be from original construction. Exterior Lower Chord (at the same location) is "NOT" bent or twisted. **See Photos 9 & 10.**

North Truss, Lower Chord, West Abutment, is almost in contact with the top of the canal wall, leaving only 1/2" of clearance. **See Photo 11.**

CITY/TOWN MONTAGUE	B.I.N. OR2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-OR2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

REMARKS

Item 59.5.c - Web Members

North Truss, Northeast End Post, Interior Web Member Base, is bent from collision damage.

Item 59.5.g - End Posts

Northeast End Post, interior vertical web member base, is bent from collision damage. **See Photo 12.**

Item 59.11 - Pins, Snap Rings

Panel connections between each Truss is held in place by 10 pins with snap rings on each end of the pin.

A few of these snap rings are corroded.

Item 59.14 - Paint/Coating

Galvanized Coating on the entire superstructure is fading. **See Photos 5, 6, & 7.**

SuperStructure Collision Notes

There is minor collision damage to the northeast corner of the bridge. See Photo 12.

ITEM 60 - SUBSTRUCTURE

Item 60.1 - Abutments

Item 60.1.b - Bridge Seats

West Bridge Seat is covered with road sand and dead vegetation. **See Photos 9 & 10.**

Item 60.1.c - Backwalls

Top of the Backwalls are the concrete headers at the deck ends.

East Concrete Header, top South End, is spalled. **See Photo 13.**

Item 60.1.d - Breastwalls

East & West Stub Abutments for this bridge are 6' to 8' behind the canal walls.

East Breastwall, under the south truss, has a 4' long x up to 1/8" wide horizontal crack. **See Photo 14.**

Item 60.1.f - Slope Paving/Rip-Rap

Stub Abutments for this bridge are behind the concrete canal walls, which provide protection for both abutments.

SubStructure Undermining Notes

East stub abutment rests on 1" diameter stone and piles. The breastwall is 24' wide x 8' deep from the front face to the back surface. The base of the breastwall is undermined, 18' wide x up to 1' high x up to 20" penetration. See Photo 15.

ITEM 61 - CHANNEL AND CHANNEL PROTECTION

Item 61.2 - Embankment Erosion

East Breastwall is undermined along the front face, 24' length x 1' height x 20" penetration. **See Photo 15.**

Item 61.3 - Debris

Canal has miscellaneous debris (tires, logs, bikes, etc).

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

REMARKS

TRAFFIC SAFETY

Item 36a - Bridge Railing

Refer to Item 58.8. - Railing.

Item 36b - Transitions

Approach guardrail travels across the bridge from approach to approach, with no transition.

Item 36c - Approach Guardrail

Approach guardrails consist of single panel steel W-beam on steel H-posts with steel offset blocks.

Southwest & Southeast approach guardrails have some scrapes.

Item 36d - Approach Guardrail Ends

Southwest Approach Guardrail continues beyond the limits of the bridge.

Northwest, Northeast, & Southeast approach guardrails have terminal ends.

Northwest Approach Guardrail End has collision damage. **See Photo 16.**

Sketch / Photo Log

- Sketch 1 : Plan
- Sketch 2 : South Elevation
- Sketch 3 : Cross Section
- Sketch 4 : ACROW Panel Details
- Sketch 5 : Steel Deck Panel Unit with five longitudinal joists (stringers)
- Photo 1 : West Approach, has two "DO NOT ENTER" signs along with a "Advance" Weight Posting.
- Photo 2 : Steel Deck Panels have some pack rusting, between top flange of the fascia joints and steel panels. A few Deck Panels have through holes near the outer edges of the panels.
- Photo 3 : Deck Underside has rust delamination with section loss of some fascia stringers. Stringers have rust holes through the webs and bottom flanges.
- Photo 4 : Northeast corner of the Steel Curb is bent due to collision damage.
- Photo 5 : Floorbeams have areas of minor surface rust. West Abutment is undermined.
- Photo 6 : Some Floorbeams, are slightly lifting up from Floorbeam Bracing System. Floorbeam Bracing System has areas of light rust staining.
- Photo 7 : Top surface of Upper Chords have areas of light rust staining.
- Photo 8 : Lower Cord has a few small dents scattered throughout the bridge.
- Photo 9 : North Truss, Lower Interior Cord, East Back Wall, is bent and twisted. This appears to be from original construction.
- Photo 10 : North Truss, Lower Exterior Cord, East Back Wall is "NOT" bent or twisted.
- Photo 11 : North Truss, Lower Chord, West Abutment, is almost in contact with the top of the canal wall, leaving only 1/2" of clearance.
- Photo 12 : Northeast End Post, interior vertical web member base, is bent from collision damage.
- Photo 13 : East Concrete Header, South End, is spalled.
- Photo 14 : East Breastwall, under South Truss, has a 4' long x up to 1/8" wide horizontal crack.
- Photo 15 : East Breastwall is undermined along the front face with up to 20" penetration.
- Photo 16 : Northwest Approach Guardrail End has collision damage at the bridge abutment.

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	---------------------------------------	---------------------------------


SKETCHES



Sketch 1: Plan

CITY/TOWN MONTAGUE	B.I.N. OR2	BR. DEPT. NO. M-28-16A	8-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	---------------------------------------	---------------------------------

SKETCHES



Sketch 2: South Elevation

CITY/TOWN
MONTAGUE


B.I.N.
0R2

BR. DEPT. NO.
M-28-16A

8-STRUCTURE NO.
M2816A-0R2-MUN-NBI

INSPECTION DATE
SEP 23, 2019

SKETCHES



TYPICAL SECTION

Sketch 3: Cross Section

CITY/TOWN
MONTAGUE


B.I.N.
0R2

BR. DEPT. NO.
M-28-16A

8-STRUCTURE NO.
M2816A-0R2-MUN-NBI

INSPECTION DATE
SEP 23, 2019

SKETCHES




Sketch 4: ACROW Panel Details


CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	---------------------------------------	---------------------------------

SKETCHES

Keirb Unit



Deck Unit



Sketch 5: Steel Deck Panel Unit with five longitudinal joists (stringers)

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS



Photo 1: West Approach, has two "DO NOT ENTER" signs along with a "Advance" Weight Posting.



Photo 2: Steel Deck Panels have some pack rusting, between top flange of the fascia joints and steel panels. A few Deck Panels have through holes near the outer edges of the panels.

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS

Photo 3: Deck Underside has rust delamination with section loss of some fascia stringers. Stringers have rust holes through the webs and bottom flanges.



Photo 4: Northeast corner of the Steel Curb is bent due to collision damage.

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS



Photo 5: Floorbeams have areas of minor surface rust. West Abutment is undermined.



Photo 6: Some Floorbeams, are slightly lifting up from Floorbeam Bracing System. Floorbeam Bracing System has areas of light rust staining.

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS



Photo 7: Top surface of Upper Chords have areas of light rust staining.



Photo 8: Lower Cord has a few small dents scattered throughout the bridge.

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	---------------------------------------	---------------------------------

PHOTOS



Photo 9: North Truss, Lower Interior Cord, East Back Wall, is bent and twisted. This appears to be from original construction.



Photo 10: North Truss, Lower Exterior Cord, East Back Wall is "NOT" bent or twisted.

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS



Photo 11: North Truss, Lower Chord, West Abutment, is almost in contact with the top of the canal wall, leaving only 1/2" of clearance.



Photo 12: Northeast End Post, interior vertical web member base, is bent from collision damage.

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS

Photo 13: East Concrete Header, South End, is spalled.




Photo 14: East Breastwall, under South Truss, has a 4' long x up to 1/8" wide horizontal crack.

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 23, 2019
-----------------------	---------------	---------------------------	--	---------------------------------

PHOTOS

Photo 15: East Breastwall is undermined along the front face with up to 20" penetration.




Photo 16: Northwest Approach Guardrail End has collision damage at the bridge abutment.

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 17, 2020
-----------------------	---------------	---------------------------	---------------------------------------	---------------------------------

SKETCHES

DECK PANEL AND LONGITUDINAL JOIST DEFICIENCIES



→ Inaccessible due to no clearance ←


- ⊗ : Loose Deck Panel to Floorbeam Connection Bolt
- +—+— : Tear in Deck
- : Hole in Deck
- : Longitudinal Joists with Heavy Section Loss
- : Longitudinal Joists with Heavy Rust and Minor Section Loss
- 1: Stringers are buckled $\frac{1}{8}$ " laterally up to 3"H
- 2: (2) tears up to 1"L x $\frac{1}{2}$ "W
- 3: (1) 4'L x 2"W hole, (2) tears up to 9"L
- 4: (1) 9"L tear
- 5: (10) holes up to $\frac{1}{2}$ " diameter, (1) 2" diameter hole, (2) tears up to 6"L

Sketch 7: Deck Panel and Longitudinal Joist Deficiencies - Panels 1 through 6

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 17, 2020
-----------------------	---------------	---------------------------	--	---------------------------------

SKETCHES

DECK PANEL AND LONGITUDINAL JOIST DEFICIENCIES




- ⊗ : Loose Deck Panel to Floorbeam Connection Bolt
- : Tear in Deck
- : Hole in Deck
- ~~~~~: Longitudinal Joists with Heavy Section Loss
- : Longitudinal Joists with Heavy Rust and Minor Section Loss
- 1: Verified Deck Unit Fascia Stringer tack welds failed
- 2: 1/2" diameter hole

Sketch 8: Deck Panel and Longitudinal Joist Deficiencies - Panels 7 through 12

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 17, 2020
-----------------------	---------------	---------------------------	--	---------------------------------

SKETCHES

DECK PANEL AND LONGITUDINAL JOIST DEFICIENCIES




- ⊗ : Loose Deck Panel to Floorbeam Connection Bolt
- - - : Tear in Deck
- : Hole in Deck
- (with oval) : Longitudinal Joists with Heavy Section Loss
- - - (with oval) : Longitudinal Joists with Heavy Rust and Minor Section Loss
- 1 : Stringers are buckled $\frac{1}{8}$ " laterally up to 3"H

Sketch 9: Deck Panel and Longitudinal Joist Deficiencies - Panels 13 through 18

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 17, 2020
-----------------------	---------------	---------------------------	---------------------------------------	---------------------------------

SKETCHES

DECK PANEL AND LONGITUDINAL JOIST DEFICIENCIES




- ⊗ : Loose Deck Panel to Floorbeam Connection Bolt
- : Tear in Deck
- : Hole in Deck
- : Longitudinal Joists with Heavy Section Loss
- - - : Longitudinal Joists with Heavy Rust and Minor Section Loss
- 1 : Stringers are buckled $\frac{1}{8}$ " laterally up to 3"H

Sketch 10: Deck Panel and Longitudinal Joist Deficiencies - Panels 19 through 23

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8.-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 17, 2020
------------------------------	----------------------	----------------------------------	---	--

SKETCHES

DECK PANEL AND LONGITUDINAL JOIST DEFICIENCIES




- ⊗ : Loose Deck Panel to Floorbeam Connection Bolt
- : Tear in Deck
- : Hole in Deck
- - - : Longitudinal Joists with Heavy Section Loss
- - - : Longitudinal Joists with Heavy Rust and Minor Section Loss

Sketch 11: Deck Panel and Longitudinal Joist Deficiencies - Panels 24 through 28

CITY/TOWN MONTAGUE	B.I.N. 0R2	BR. DEPT. NO. M-28-16A	8-STRUCTURE NO. M2816A-0R2-MUN-NBI	INSPECTION DATE SEP 17, 2020
------------------------------	----------------------	----------------------------------	--	--

SKETCHES

DECK PANEL AND LONGITUDINAL JOIST DEFICIENCIES



- ⊗ : Loose Deck Panel to Floorbeam Connection Bolt
- : Tear in Deck
- : Hole in Deck
- : Longitudinal Joists with Heavy Section Loss
- - - - - : Longitudinal Joists with Heavy Rust and Minor Section Loss
- 1: Verified Deck Unit Fascia tack welds failed
- 2: 5" long tear
- 3: Full panel width x up to 2"D gouge at east end

Sketch 12: Deck Panel and Longitudinal Joist Deficiencies - Panels 29 through 33